



NOTES: MANHOLE NOT TO BE LOCATED WITHIN THE OVERFLOW OF THE DETENTION BASIN.

RESTRICTOR PLATE MANHOLE

Issued		
By	Revised	Date
NL/DS		7/8/11
MJ		6/24/14

**VILLAGE OF GURNEE
ENGINEERING DIVISION**

Approved by:	
	SD 7/8/11
	SD 6/24/14