

| Long Hill Road | | | | |
|-----------------------|---------------------------|-------------|----------------------|--|
| Address Number | Side of the Street | Area | Basic Impacts | Notes |
| 469 | East | Area 1 | | |
| 475 | East | Area 1 | T, RW | |
| 481 | East | Area 1 | T, F | - The fence running around the channel may need to be removed. |
| 487 | East | Area 1 | T, R | |
| 493 | East | Area 1 | R, RW | |
| 499 | East | Area 1 | T, R, RW | |
| 503 | East | Area 1 | T | - The stone path running down the middle of the channel may need to be removed, and the channel may need to be regraded. |
| 507 | East | Area 1 | T, R, F | - The stone path running down the middle of the channel may need to be removed, and the channel may need to be regraded. |
| 513 | East | Area 1 | F | |
| 519 | East | Area 1 | T, R | - The shed in the easement may need to be removed, and the channel may need to be regraded. |
| 525 | East | Area 1 | T, R, RW | - The retaining wall may need to be removed from the easement and the channel may need to be regraded to better convey flow. |
| 531 | East | Area 1 | T, R, F | - The small arching footbridge may need to be removed from the channel. |
| 537 | East | Area 1 | T, F | |
| 543 | East | Area 1 | T, R, F | |
| 587 | North | Area 1 | T, R, F, RW | - The tiled path along the bottom of the channel may need to be removed to restore the channel. |
| 593 | North | Area 1 | T, R, RW | - The tiled path along the bottom of the channel may need to be removed to restore the channel. |

| Kings Way West | | | | |
|-----------------------|---------------------------|-------------|----------------------|---|
| Address Number | Side of the Street | Area | Basic Impacts | Notes |
| 4812 | West | Area 1 | T, R | |
| 4817 | East | Area 2 | T, R, RW | |
| 4818 | West | Area 1 | T, R, F | |
| 4823 | East | Area 2 | F | |
| 4824 | West | Area 1 | T, R, F | |
| 4829 | East | Area 2 | T, F | |
| 4832 | West | Area 1 | T, R | |
| 4835 | East | Area 2 | T, R, F, RW | - The construction to restore The drainage channel may have impacts on the pool. |
| 4838 | West | Area 1 | T, R | |
| 4839 | East | Area 2 | T, R, F, RW | - The shed and the retaining structure may need to be removed from the easement, and the channel may need to be regraded to better convey flow. |
| 4843 | East | Area 2 | T, F | - The construction to restore the drainage channel may have impacts on the pool. |
| 4844 | West | Area 1 | T, R, F | |
| 4849 | East | Area 2 | T | |
| 4850 | West | Area 1 | T, R, F | |
| 4856 | West | Area 1 | T, R, RW | - The retaining wall may need to be removed from the easement and the channel may need to be regraded to better convey flow. |
| 4862 | West | Area 1 | T, R, F | |
| 4868 | West | Area 1 | | |
| 4874 | West | Area 1 | | - The small arching footbridge may need to be removed from the channel. |
| 4875 | East | Area 8 | T, R | |
| 4880 | West | Area 1 | T, R | |
| 4883 | East | Area 8 | R | |
| 4886 | West | Area 1 | T, R, RW | - A portion of the retaining wall may need to be removed from the easement for the channel to be regraded to better convey flow. |
| 4891 | East | Area 8 | R, F | |
| 4897 | East | Area 8 | F | |
| 4903 | East | Area 8 | T, R, F | |
| 4909 | East | Area 8 | T, R, F | |
| 4915 | East | Area 8 | | |

| Calvin Court | | | | |
|----------------|--------------------|--------|---------------|--|
| Address Number | Side of the Street | Area | Basic Impacts | Notes |
| 474 | West | Area 7 | | |
| 479 | East | Area 3 | T, R | |
| 486 | West | Area 2 | T | |
| 491 | East | Area 3 | T | |
| 498 | West | Area 2 | T, R, RW | - The retaining wall may need to be removed from the easement for the channel to be regraded to better convey flow. |
| 503 | East | Area 3 | T, R | - The gazebo may need to be removed from the easement and the channel may need to be regraded to better convey flow. |
| 510 | West | Area 2 | T, R | |
| 515 | East | Area 3 | T, R, F | |
| 522 | West | Area 2 | T, R | |
| 527 | East | Area 3 | T, F | |
| 534 | West | Area 2 | T, F | |
| 539 | East | Area 3 | T, R, F | |
| 546 | West | Area 2 | T | |

| Majestic Court | | | | |
|----------------|--------------------|--------|---------------|---|
| Address Number | Side of the Street | Area | Basic Impacts | Notes |
| 472 | West | Area 3 | T, R | |
| 477 | East | Area 4 | T, R, F | |
| 484 | West | Area 3 | T, R | |
| 489 | East | Area 4 | T, R | - The shed may need to be removed from the easement, and the channel may need to be regraded to better convey flow. |
| 496 | West | Area 3 | T, R | |
| 501 | East | Area 4 | R, F | |
| 508 | West | Area 3 | T, R | - The shed may need to be removed from the easement, and the channel may need to be regraded to better convey flow. |
| 513 | East | Area 4 | R, F | |
| 520 | West | Area 3 | T, R, F | - The shed may need to be removed from the easement, and the channel may need to be regraded to better convey flow. |
| 525 | East | Area 4 | R | |
| 532 | West | Area 3 | T, R, F | |
| 537 | East | Area 4 | T, R | |
| 544 | West | Area 3 | T, R, F | |

| Lexington Square West | | | | |
|-----------------------|--------------------|--------|---------------|---|
| Address Number | Side of the Street | Area | Basic Impacts | Notes |
| 628 | East | Area 5 | T | |
| 631 | West | Area 8 | | |
| 637 | West | Area 8 | | |
| 640 | East | Area 5 | T, R | |
| 643 | West | Area 8 | | |
| 646 | East | Area 5 | | |
| 649 | West | Area 8 | T, R | |
| 652 | East | Area 5 | T, R | |
| 655 | West | Area 8 | T, R | |
| 658 | East | Area 5 | R | |
| 661 | West | Area 8 | T, R | |
| 664 | East | Area 5 | T, R, RW | - The retaining wall may need to be removed from the easement for the channel to be regraded to better convey flow. |
| 667 | West | Area 8 | R | |

| Lexington Square East | | | | |
|-----------------------|--------------------|--------|---------------|-------|
| Address Number | Side of the Street | Area | Basic Impacts | Notes |
| 574 | West | Area 5 | T, R, F | |
| 578 | West | Area 5 | T, R, F | |
| 581 | East | Area 6 | | |
| 582 | West | Area 5 | T, R, F | |
| 585 | East | Area 6 | T | |
| 586 | West | Area 5 | T, R, F | |
| 589 | East | Area 6 | | |
| 590 | West | Area 5 | T, F | |
| 593 | East | Area 6 | T | |
| 594 | West | Area 5 | T | |
| 597 | East | Area 6 | T, F | |

| Cross Court | | | | |
|----------------|--------------------|----------------|---------------|-------|
| Address Number | Side of the Street | Area | Basic Impacts | Notes |
| 470 | West | Area 4, Area 7 | T, R | |
| 482 | West | Area 4 | T, R, F | |
| 494 | West | Area 4 | T, R | |
| 506 | West | Area 4 | T | |
| 518 | West | Area 4 | T, R, F | |
| 530 | West | Area 4 | T, R, F | |
| 542 | West | Area 4 | T, R | |
| 554 | West | Area 4 | T, R | |

| Cross Court | | | | |
|----------------|--------------------|--------|---------------|-------|
| Address Number | Side of the Street | Area | Basic Impacts | Notes |
| 582 | West | Area 6 | T | |
| 590 | West | Area 6 | T | |
| 598 | West | Area 6 | T, R, F | |
| 606 | West | Area 6 | T, R, F | |

| Providence Road | | | | |
|-----------------|--------------------|--------|---------------|---|
| Address Number | Side of the Street | Area | Basic Impacts | Notes |
| 4671 | South | Area 6 | T, R | |
| 4672 | North | Area 4 | T, R, F | |
| 4697 | South | Area 6 | T, F | |
| 4698 | North | Area 4 | T, R | - The hedge along the channel may need to be removed for the channel to be regraded to better convey flow. |
| 4725 | South | Area 5 | F | |
| 4755 | South | Area 5 | T, R, RW | - The retaining wall may need to be removed from the easement for the channel to be regraded to better convey flow. |
| 4756 | North | Area 3 | T | |
| 4791 | South | Area 8 | R | |
| 4809 | South | Area 8 | T, F | |
| 4810 | North | Area 2 | T, R, F, RW | |

| Middle Road | | | | |
|----------------|--------------------|--------|---------------|---|
| Address Number | Side of the Street | Area | Basic Impacts | Notes |
| 4665 | South | Area 7 | T, F | |
| 4667 | South | Area 7 | | |
| 4679 | South | Area 7 | F | |
| 4691 | South | Area 7 | F | |
| 4703 | South | Area 7 | F | |
| 4715 | South | Area 7 | F | |
| 4727 | South | Area 7 | R, F | |
| 4739 | South | Area 7 | R, F | - The shed may need to be removed from the easement, and the channel may need to be regraded to better convey flow. |
| 4751 | South | Area 7 | R | |
| 4763 | South | Area 7 | R | |
| 4775 | South | Area 7 | R, F | |
| 4787 | South | Area 7 | | |
| 4799 | South | Area 7 | F | |
| 4811 | South | Area 7 | F | |
| 4837 | South | Area 1 | | |
| 4851 | South | Area 1 | | |